

MPX troubleshooting flowchart Dodge 2500/3500/4500/5500 2015 and above (Using Snowplow 6 wires)

Underhood Installation

(module installed under the vehicle's hood)

Important Note:

- Use Power Probe III tool to troubleshoot the MPX system.
- https://www.youtube.com/watch?v=FuzfCOlA1Vw Link for Power Probe III tool instructions
- Update the modular box by updating tool (53707-M) if it was installed before 2017.
- See last page for more information on updating the modular box.
- See second page for more information on the Underhood Troubleshooting tool.



Links fore removing & reinstalling pins from Underhood harness plugs



https://www.youtube.com/watch?v=BB6tE096HkQ




Link for removing & reinstalling pins from female plug https://www.youtube.com/watch?v=VAm0plQIegs



53706-M (Underhood Troubleshooting tool kit)

To be plugged together all the time for troubleshooting underhood installation on Dodge 6 wires (2015 and above)



Terminal on the tool	Functions of the terminal
AA1	High Beam
AA2	Low Beam
AB1	Driver Side Turn
AB2	Driver Side Park
AC1	Curb Side Turn
AF1	Trigger
BC3	Ignition
BJ2	Power wire (Battery connection)
BJ3	Power wire (Battery connection)
BK1	Solenoid (Brown wire)

Note: Terminal Marked with Black color are Grounds.

Snowplow 6 wires

Under Vehicle's fuse box









Lift the box and find 6 wires, attach them to the harness as shown



Vehicle's Harness

Plug the harness in the control module; install module on the fuse box

White/Violet (Turn DS)

Black / Violet

Black / Lt. Green (LB)

- Install VELCRO stick back tape on the bottom of the module and on top of the fuse box

Light Adapter Harness

Turn DS Lt. Blue

Black /

(SnowPlow Enable wire)

Violet/Brown (Turn CS)

Park (White / Brown)

White / Brown (Park)

Control Module Box

Vehicle Harness **Light Adapter Harness Function** Black/Lt. Blue To Black / Lt. Blue High Beam Connect Low Beam Black/Lt. Green To Black / Lt. Green Connect Park White/Brown White / Brown Connect To Lt. Blue White/Violet To DS Turn Connect CS Turn Lt. Blue Violet/Brown To Connect Snowplow Black/Violet To Black / Violet Connect Enable wire

HB Relay

Turn CS

Lt. Blue

LB Relay LB (Black / Lt.Green)

HB (Black / Lt. Blue)

LEGEND

DS- Driver Side

CS - Curb Side

HB - High Beam


LB - Low Beam



Click on the link below to refer to the specific troubleshooting step:

- Marker/Position lights on one side of plow headlights is not working.
- Marker/Position lights on both the sides of plow headlights are not working
- High beam / Low beam on one side of the plow headlight is not working.
- High beam on both the sides of plow headlights are not working.
- Low beam on both the sides of plow headlights are not working.
- Turn Signal on Driver side of the plow headlight is not working.
- Turn Signal on Curb side of the plow headlight is not working.
- Plow does not operate and lights on the plow are not working.
- Plow does not operate.
- Lights do not transfer to the plow.
- Individual functions on the plow are not working.
- Controller lights keep on changing.






Click on https://www.youtube.com/watch?v=ErBX0E5GpeE&feature=youtu.be to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI






Click on the link https://www.youtube.com/watch?v=0oSPpkrZCOE & https://www.youtube.com/watch?v=-CD8N07SB_s to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI






Click on link https://www.youtube.com/watch?v=7wruoLUVfdI to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI






Click on the link https://www.youtube.com/watch?v=0oSPpkrZCOE & https://www.youtube.com/watch?v=NDnCfwl3ftU to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI






Click on the link https://www.youtube.com/watch?v=0oSPpkrZCOE & https://www.youtube.com/watch?v=Qyg0_3bFPGE to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI






Click on the link https://www.youtube.com/watch?v=WckVZFUPIVQ to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q

Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI






Click on the link https://www.youtube.com/watch?v=2yG1dkX8q9Y to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q


Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI






Click on the link https://www.youtube.com/watch?v=0oSPpkrZCOE to watch the video of this specific troubleshooting step.





Click on the link https://www.youtube.com/watch?v=0oSPpkrZCOE to watch the video of this specific troubleshooting step.





Connect "BJ2" with "AF1" by plugging the connectors together on the tool (refer to Page 2). After connecting, check pins on the Underhood Troubleshooting tool:
-12 V must be present on terminal "AA1" when High Beam is turned on the truck.

- -12 V must be present on the terminal "AA2" when Low Beam is turned on the
- If the voltage is not present check wire connection and relays condition on Dodge 6 wires, make sure they are connected accordingly (refer to Page 3 for proper connection.) Repair/Replace the realys or even the light adapter harness if necessary. Problem solved?

Replace the modular box or lift frame harness.


Restart truck's ignition after every step of troubleshooting.

Click on the link https://www.youtube.com/watch?v=0oSPpkrZCOE to watch the video of this specific troubleshooting step.

Link for 800084 headlights: https://www.youtube.com/watch?v=LJlgbdwop8Q


Link for 800085 headlights: https://www.youtube.com/watch?v=fn09WLSG-vI





Click on the link https://www.youtube.com/watch?v=K1ERrFWnUw0 to watch the video of this specific troubleshooting step.






Click on the link https://www.youtube.com/watch?v=gKqEarX4FrQ to watch the video of this specific troubleshooting step.



Connectors alignment for the MPX system





Tool for updating MPX module box (53707-N)



Check the link below to see step by step procedure on how to update the module box on your truck:

https://www.youtube.com/watch?v=nGSTAm8hZ9Y